



LBC.1498-A

Z-5 40  
BU.2.15.70.p

Z-5 90  
BU.2.20.60.p

BU.3.20.60.p

BU.2.15.70.p

85  
AU

1163  
BU.2.15.70.p

1302  
BU.2.20.60.p

1303  
BU.2.15.70.p

1304  
BU.2.10.80.p

Z-5 21  
BU.2.15.70.p

1176  
BU.2.15.70.p

1307  
BU.2.15.70.p

1374  
BU.2.15.70.p

1375  
BU.2.10.80.p

1376  
BU.2.15.70.p

1385  
BU.2.15.70.p

112  
ZU

256  
ZU

1377  
BU.2.16.80.p

1378  
ZU

1228  
BU.2.10.80.p

1332  
BU.2.15.70.p

LBK.1498-C

1352  
BU.2.20.60.p

1353  
BU.2.10.80.p

LBK.1498-C

Z-5 60  
BU.1.10.80.v

Z-5 63  
BU.2.15.70.p

1354  
BU.2.15.70.p

LBK.1498-C

1355  
BU.2.25.60.p

Z-5 80  
BU.2.15.70.p

1377  
SU.1.10.40.p

LBK.1498-C

1378  
SU.3.20.50.s

Z-5 27

LBK.1498-C

LBK.1498-C

1377  
BU.1.10.80.v

1378  
BU.1.15.70.v

1379  
BU.1.15.70.v

1385  
BU.1.10.80.v

100  
AU

1380  
BU.2.15.70.p

1381  
BU.2.10.80.p

LBK.1498-C

LBK.1498-C

1382  
OV.2.20.20.k

1383  
ZU

Z-5 118  
RU.0.0.95.v

Z-5 117  
RU.1.5.90.v

Z-5 119  
BU.1.7.85.v

158  
LU

LBC.C

1384  
BU.2.25.60.p

Z-5 67  
BU.2.15.70.p

Z-5 128  
BU.2.10.80.p

II - 03-32-023

SU.3.30.30.s